SRI VINAYAKA BOREWELLS

Railway Gate, Ring Road, Bhadrappa Layout, Nagashettyhalli,
Bangalore - 560 094. Cell : 9342202932, 9980002932

No.

BOREWELL COMPLETION REPORT

Date : 17/06/2014

1. Customer's Name and Address with Telephone No. : KRIDL
   AK Colony.
   Ward no. 10
2. Well Location : Dodbanusandra
3. Total Well Depth/Drilled in Ft. : 1090 ft
4. Casing Erected Ft. : 32 mts.
5. Water Struck at the Depth of : 800 ft
6. Total Yield (Measuring method "V" Notch : 1090 /Inches on "V" Noth
7. Formation of Soil / Well Water Condition : Boulders /Silt / Loose Soil / Clear. clean water
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled accordance with the company terms and condition and handed over to customer in good / satisfied / party agreed condition

Once the well handed over to party, company is no way responsible for further developments if any in the well whatsoever.

Party's Signature

I, owner of the Well / Authorised signatory fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend on nature / formation of ground water and the drilling agency no way responsible for further occurrence / changes in the bore with full satisfaction. I hereby endorse my signature.

For SRI VINAYAKA BOREWELLS

Party's Signature

Authorised Signatory

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

SRI VINAYAKA BOREWELLS

Railway Gate, Ring Road, Bhadrappa Layout, Nagashettyhalli,
Bangalore - 560 094. Cell : 9342202932, 9980002932



No.

BOREWELL COMPLETION REPORT

Date : 10/04/2014

1. Customer's Name and Address with Telephone No. : KRIDL, kallappa layout, ward no. 10
2. Well Location : Dodbamasandra
3. Total Well Depth/Drilled in Ft. : 1100 ft.
4. Casing Erected Ft. : 25 mt.
5. Water Struck at the Depth of : 780 ft.
6. Total Yield (Measuring method "V" Notch : 1100 /Inches on "V" Noth
7. Formation of Soil / Well Water Condition : Boulders /Silt / Loose Soil / Clear. Clean water
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled accordance with the company terms and condition and handed over to customer in good / satisfied / party agreed condition

Once the well handed over to party, company is no way responsible for further developments if any in the well whatsoever.

Party's Signature

I, owner of the Well / Authorised signatory fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend on nature / formation of ground water and the drilling agency no way responsible for further occurrence / changes in the bore with full satisfaction. I hereby endorse my signature.

For SRI VINAYAKA BOREWELLS

Party's Signature

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Dinesh

Authorised Signatory

SRI VINAYAKA BOREWELLS

Railway Gate, Ring Road, Bhadrappa Layout, Nagashettyhalli,
Bangalore - 560 094. Cell : 9342202932, 9980002932

No.

BOREWELL COMPLETION REPORT

Date : 11/04/2014

1. Customer's Name and Address : KRIDL
   with Telephone No. Yellamandamma badavane
   Ward no. 10.
2. Well Location : Ramchandrapura
3. Total Well Depth/Drilled in Ft. : 980 ft.
4. Casing Erected Ft. : 99 mts.
5. Water Struck at the Depth of : 810 ft.
6. Total Yield (Measuring method "V" Notch : 980 /Inches on "V" Noth
7. Formation of Soil / Well Water Condition : Boulders /Silt / Loose Soil / Clear. clear water
8. At the Depth of : .....
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled accordance with the company terms and condition and handed over to customer in good / satisfied / party agreed condition

Once the well handed over to party, company is no way responsible for further developments if any in the well whatsoever.

Party's Signature

I, owner of the Well / Authorised signatory fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend on nature / formation of ground water and the drilling agency no way responsible for further occurrence / changes in the bore with full satisfaction. I hereby endorse my signature.

For SRI VINAYAKA BOREWELLS

Party's Signature

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Authorised Signatory